

MERCEDES-BENZ E 220 D 194 HK AUTOMAT 2WD

TESTDATO: 16.12.2025

KODE: 1904808



AE52569



142 848 KM



28.07.2017

Førstegang registrert



Diesel

CHASSISNR: WDD2132041A155389

BRUKTIMPORT: Nei

KJØRETØY: Personbil

FRIST FOR PKK: 30.09.2027

NBF Tilstandsrapport er utarbeidet av Norges Bilbransjeforbund og Forbrukerrådet.

NBF Tilstandsrapport gir en detaljert beskrivelse av bilens tilstand, og gir den som kjøper bilen økt trygghet ved kjøpet. Rapporten utarbeides av teknisk kyndig personell, som gjør en grundig kontroll og inspeksjon.

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet hensyntatt bilens alder og kilometerstand, med det utstyret som er i og på bilen.

Se mer om forutsetningene for vurderingen og andre vilkår på siste side.



## OPPSUMMERT STATUS PÅ KJØRETØY



Ingen anmerkning



Anmerkning(er)



IDENTITET



ASSISTENTSYSTEMER OG DIAGNOSE



EKSTERIØR



LYS



MOTOR



HJULOPPHENG/STYRING



BREMSER



GIR OG DRIVLINJE



INTERIØR



OPPLYSNINGER/KLARGJØRING



| Punkt        |             | Beskrivelse    | Plassering |
|--------------|-------------|----------------|------------|
| 1. EKSTERIØR |             |                |            |
| 1.1          | Dekk/Felger | kantkjørt felg |            |



1.1 Kantkjørt felg





Mercedes-Benz

**Service report 1**  
Mercedes-Benz

Bertel O. Steen Østfold AS,  
Sarpsborg  
Hornskinnveien 98  
Sarpsborg

Date: 31.01.2018  
Rep.-order-no.: 303587  
Mileage: 51345 km

**Performed services**

|                    |           |
|--------------------|-----------|
| Service            | Service A |
| Workshop code      | 505       |
| Remaining time     | 186 Days  |
| Remaining distance | 100 km    |

**Oil quality/viscosity**

|             |            |
|-------------|------------|
| Description | Engine oil |
| Oil quality | 229.51     |
| Viscosity   | 5W-30      |

**Replaced / renewed**

Engine: oil and filter change ☒

**Until next service**

Mercedes-Benz Mobilo ☒

Warr. against rusting through ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**

Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**

Accomplished ☒

Mercedes-Benz

**Service report 2**  
Mercedes-Benz

Bertel O. Steen Østfold AS,  
Sarpsborg  
Hornskinnveien 98  
Sarpsborg

Date: 26.10.2018  
Rep.-order-no.: 303587  
Mileage: 51345 km

**Performed services**

|                    |           |
|--------------------|-----------|
| Service            | Service B |
| Workshop code      | 880E      |
| Remaining time     | 90 Days   |
| Remaining distance | ~1200 km  |

**Oil quality/viscosity**

|             |            |
|-------------|------------|
| Description | Engine oil |
| Oil quality | 229.52     |
| Viscosity   | 5W-30      |

**Replaced / renewed**

Engine: oil and filter change ☒

**Until next service**

Mercedes-Benz Mobilo ☒

Warr. against rusting through ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**

Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**

Accomplished ☒

Mercedes-Benz

**Service report 3**  
Mercedes-Benz

Bertel O. Steen Østfold AS,  
Sarpsborg  
Hunnikneveien 98  
Sarpsborg

Date  
Rep.-order-no.  
Mileage

21.10.2019  
313714  
65888 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service A  
D00  
5 Days  
10457 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.52  
5W-30

**Replaced / renewed**  
Engine oil and filter change  
Brake fluid replaced

☒ ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

Mercedes-Benz

**Service report 4**  
Mercedes-Benz

Bertel O. Steen Østfold AS,  
Sarpsborg  
Hunnikneveien 98  
Sarpsborg

Date  
Rep.-order-no.  
Mileage

28.10.2020  
5644652  
80317 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service B  
S08  
10 Days  
1000 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.52  
5W-30

**Replaced / renewed**  
Dust filter replaced  
Air filter element replaced /  
Rear axle: Oil change  
Fuel filter replaced  
Engine: oil and filter change

☒ ☒ ☒ ☒ ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

Mercedes-Benz

**Service report 5**  
Mercedes-Benz

Bertel O. Steen Østfold AS,  
Sarpsborg  
Hunnikneveien 98  
Sarpsborg

Date  
Rep.-order-no.  
Mileage

11.10.2022  
817171  
10679 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service A  
D00  
5 Days  
10457 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.52  
5W-30

**Replaced / renewed**  
Engine oil and filter change  
Brake fluid replaced

☒ ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

Mercedes-Benz

**Service report 6**  
Mercedes-Benz

Slattem Kristiansund AS  
Verkstedsveien 4  
Kristiansund

Date  
Rep.-order-no.  
Mileage

11.10.2022  
7719278  
103679 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service B  
606  
8 Days  
12029 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.52  
5W-30

**Replaced / renewed**  
Dust filter replaced  
Engine: oil and filter change

☒ ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

Mercedes-Benz

**Service report 7**  
Mercedes-Benz

Slattem Kristiansund AS  
Verkstedsveien 4  
Kristiansund

Date  
Rep.-order-no.  
Mileage

05.10.2023  
8995374  
118107 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service A  
SD0J  
4 Days  
10572 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.31  
5W-30

**Replaced / renewed**  
Automatic transmission: oil  
and filter change  
Engine: oil and filter change

☒ ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

Mercedes-Benz

**Service report 8**  
Mercedes-Benz

Slattem Kristiansund AS  
Verkstedsveien 4  
Kristiansund

Date  
Rep.-order-no.  
Mileage

04.09.2024  
123145  
128543 km

**Performed services**  
Service  
Workshop code  
Remaining time  
Remaining distance

Service B  
ODW  
28 days  
14600 km

**Oil quality/viscosity**  
Description  
Oil quality  
Viscosity

Engine oil  
229.52

**Replaced / renewed**  
Perform Service B with Plus  
package ☒

**Until next service**  
Mercedes-Benz Mobilo  
Warr. against rusting through

☒ ☒

**Service-intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

3 / 11  
16:00

Mercedes-Benz

**Digital Service Report**

**Vehicle Info**  
Vehicle: E 220 d  
First reg. date: 26.07.2017  
FIN: WDD2110041A155389

**Next Service**  
08.2026 164914 km  
(Please note: The scheduled maintenance for your vehicle (owner's manual, service bulletin and service interval indicator) do the performance of the Service.)

**Service report #**  
Mercedes-Benz Stattem Kristiansund AS  
Verkstedveien 4  
Kristiansund

**Performed services**  
Service: Service A  
Workshop code: 505  
Remaining time: 13 Days  
Remaining distance: 13600 km

**Oil quality/viscosity**  
Description: Engine oil  
Oil quality: 229 52  
Viscosity:

**Replaced / renewed**  
Perform Service A with Plus package ☒  
Extra work for Service B: ☒  
Replace brake fluid

**Until next service**  
Mercedes-Benz Mobilio ☒  
Warn: against rusting through ☒

**Service intervals in accordance with Mercedes-Benz AG specification**  
Complied with ☒

**Addwork in accordance with Mercedes-Benz AG specification**  
Accomplished ☒

### KJØRETØYDATA

|                        |     |                   |             |
|------------------------|-----|-------------------|-------------|
| ANTALL NØKLER          | 2   | ANTALL LADEKABLER | 0           |
| TIDLIGERE STØRRE SKADE | Nei | TIDLIGERE BRUK    | Normal bruk |

### PRØVEKJØRING

| PRØVEKJØRT | HASTIGHET | TESTFORHOLD |
|------------|-----------|-------------|
| Ja         | 80        | Tørt        |

### DEKK OG BREMSER

|                            |              |                            |              |
|----------------------------|--------------|----------------------------|--------------|
| PRODUKSJONSDATO SOMMERDEKK | Uke 52, 2023 | PRODUKSJONSDATO VINTERDEKK | Uke 25, 2022 |
|----------------------------|--------------|----------------------------|--------------|

|                              | VENSTRE FORAN | HØYRE FORAN | VENSTRE BAK | HØYRE BAK |
|------------------------------|---------------|-------------|-------------|-----------|
| MØNSTERDYBDE SOMMERDEKK (MM) | 6             | 6           | 5           | 5         |
| MØNSTERDYBDE VINTERDEKK (MM) | 6             | 6           | 5           | 5         |

### SERVICEINFORMASJON

| KOMPLETT HISTORIKK | ELEKTRONISK SERVICEHEFTE |
|--------------------|--------------------------|
| Ja                 | Ja                       |
| SISTE SERVICEDATO  | KILOMETERSTAND           |
| 20.08.2025         | 139914                   |

☒ **Kontrollert** / 
 ☐ **Ikke kontrollert** / 
 ☒ **Kontrollert, anmerkning**

## IDENTITET

- ☒ Kjennermerke
- ☒ Understellsnummer
- ☒ Dokumentasjon utstyr/godkjenning
- ☒ Nøkler

## ASSISTENTSYSTEMER OG DIAGNOSE

- ☒ Kamera
- ☒ Sensor
- ☒ Systemfunksjoner
- ☒ Diagnose
- ☒ Prøvekjøring

## EKSTERIØR

- ☒ Lakk
- ☒ Antirustbehandling
- ☒ Under bil
- ☒ Panser
- ☒ Dører
- ☒ Bakluke
- ☒ Låser/tyverisikring
- ☒ Skjermer
- ☒ Speil
- ☒ Korrosjon
- ☒ Vinduspussere/-spyler
- ☒ Verktøy/nødutstyr
- ☒ Dekk/Felger
- ☒ Hjulmuttere/-bolter
- ☒ Døråpning
- ☒ Terskler/innlastningssone
- ☒ Støtfanger
- ☒ Grill
- ☒ Tak
- ☒ Frontvindu
- ☒ Vinduer
- ☒ Kanal
- ☒ Stolpe
- ☒ Alle flater
- ☒ Ladeluke/tanklokk

## LYS

- ☒ Lys foran
- ☒ Lys bak
- ☒ Markeringslys
- ☒ Retningslys
- ☒ Nødsignallys
- ☒ Parkeringslys
- ☒ Refleks
- ☒ Andre lys

## MOTOR

- ☒ Avgass
- ☒ Batteri(er)
- ☒ Drivstoffanlegg/-ledninger
- ☒ Dynamo/lading
- ☒ Eksosanlegg
- ☒ Elektroniske styresystemer
- ☒ Kjølesystem/vannpumpe
- ☒ Lekkasjer
- ☒ Motorfester/-demper
- ☒ Oljenivå/røykutvikling
- ☒ Service
- ☒ Startmotor
- ☒ Trekkraft
- ☒ Turbo
- ☒ Ladeluftkjøler
- ☒ Kompressor
- ☒ Dieselpumpe/dyser/gløding
- ☒ Motor

## HJULOPPHENG/STYRING

- ☒ Retningsstabilitet/selvoppretting
- ☒ Ratt/styringsmekanisme
- ☒ Hjullager
- ☒ Fjærer/støtdemper
- ☒ Ledd
- ☒ Stabilisatorer/stag
- ☒ Forstilling
- ☒ Bakstilling

## BREMSE

- ☒ Bremsfunksjon
- ☒ Parkeringsbrems
- ☒ Bremskraftforsterker
- ☒ Bremsvæske
- ☒ Lekkasjer
- ☒ Rør/slanger
- ☒ Skiver
- ☒ Bremseskjold

## GIR OG DRIVLINJE

- ☒ Girkasse
- ☒ Differensial
- ☒ Clutch/kobling/svinghjul
- ☒ Aksler
- ☒ Fordelingskasse

## INTERIØR

- ☒ Dashbord
- ☒ Instrumenter og brytere
- ☒ Midtkonsoll/midtarmlene
- ☒ Dørtrekk
- ☒ Seter
- ☒ Taktrekk
- ☒ Tepper/bekledning
- ☒ Vindusheiser
- ☒ Bilbelte
- ☒ Varme/AC/Klima
- ☒ Signalhorn/Lydsignal
- ☒ Multimedia
- ☒ Multifunksjonsratt
- ☒ Ratt
- ☒ Deksel

## OPPLYSNINGER/KLARGJØRING

- ☒ Opplysninger
- ☒ Interiør
- ☒ Øvrig utstyr/klargjøring
- ☒ Annet

Det tas forbehold om mulige avvik i kontrollpunktene avhengig av biltype og modellvariant

## Vilkår, tilstandsrapport

### Hva som er vurdert, forutsetninger for vurderingen

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet med det utstyret som var i og på bilen.

Den tekniske vurderingen av bilen er gjort med utgangspunkt i bilens alder og kjørelengde. Rapporten beskriver om bilens tilstand vurderes som normal ut fra bilens alder og kjørelengde og/eller om det er anmerkninger eller øvrige kommentarer. Kontrollpunktene som er vurdert er listet opp i rapporten.

Bilen er ikke demontert ved vurderingen, og tilstandsrapporten påpeker dermed ikke eventuelle feil som kun kan avdekkes ved demontering eller ved lengre tids bruk ut over ordinær prøvekjøring.

Kapasiteten på driftsbatteriet på el- og hybridbiler er ikke målt, og er derfor ikke en del av tilstandsrapport

Feilmeldinger som bilens produsent har gitt tilgang til og som er tilgjengelige på vurderingstidspunktet/testtidspunktet er avlest. Avlesing av feilmeldinger skjer med tilgjengelig diagnoseutstyr. Ved usikkerhet omkring feilkodene anbefales videre undersøkelser.

Bilen er prøvekjørt, men kun ved en kortere tur. Tekniske egenskaper ved bilen som forutsetter spesielle kjøreforhold er kun vurdert om kjøreforholdene på vurderingstidspunktet gjorde dette mulig.

Periodiske feil og avvik for eksempel ved oljeforbruket på fossile biler kan forekomme uten at dette kan avdekkes, ettersom vurderingen kun gir et øyeblikksbilde av bilens tilstand.

---

Sted og Dato

---

Sted og Dato

---

Signatur selger

---

Signatur kjøper

Selger og kjøper bekrefter med sine underskrifter at ved inngåelsen av kjøpsavtalen ble tilstandsrapporten gjennomgått med kjøper, og at det spesielt ble informert om avvik fra kravene i forbrukerkjøpslovens § 15 i de tilfeller slike fremkommer i rapporten, og at kjøper aksepterer disse avvikene.