

MERCEDES-BENZ E 220 D 194 HK AUTOMAT 2WD
TESTDATO: 16.12.2025
KODE: 1904808


AE52569


142 848 KM


28.07.2017
Førstegang registrert


Diesel

CHASSISNR: WDD2132041A155389	BRUKTIMPORT: Nei
KJØRETØY: Personbil	FRIST FOR PKK: 30.09.2027

NBF Tilstandsrapport er utarbeidet av Norges Bilbransjeforbund og Forbrukerrådet.

NBF Tilstandsrapport gir en detaljert beskrivelse av bilens tilstand, og gir den som kjøper bilen økt trygghet ved kjøpet. Rapporten utarbeides av teknisk kyndig personell, som gjør en grundig kontroll og inspeksjon.

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet hensyntatt bilens alder og kilometerstand, med det utstyret som er i og på bilen.

Se mer om forutsetningene for vurderingen og andre vilkår på siste side.


OPPSUMMERT STATUS PÅ KJØRETØY
 Ingen anmerkning

 Anmerkning(er)

 IDENTITET 	 ASSISTENTSYSTEMER OG DIAGNOSE 
 EKSTERIØR 	 LYS 
 MOTOR 	 HJULOPPHENG/STYRING 
 BREMSER 	 GIR OG DRIVLINJE 
 INTERIØR 	 OPPLYSNINGER/KLARGJØRING 

Punkt		Beskrivelse	Plassering
1. EKSTERIØR			
1.1	Dekk/Felger	kantkjørt felg	



1.1 Kantkjørt felg





Mercedes-Benz

Service report 1
Mercedes-Benz

Bertel O. Steen Østfold AS,
Sarpsborg
Hornskinnveien 98
Sarpsborg

Date: 31.01.2018
Rep.-order-no.: 29718
Mileage: 25176 km

Performed services
Service: Service A
Workshop code: 505
Remaining time: 186 Days
Remaining distance: 100 km

Oil quality/viscosity
Description: Engine oil
Oil quality: 229.51
Viscosity: 5W-30

Replaced / renewed
Engine: oil and filter change ☒
Until next service: Mercedes-Benz Mobilo ☒
Warr. against rusting through ☒
Service-intervals in accordance with Mercedes-Benz AG specification ☒
Complied with: ☒
Addwork in accordance with Mercedes-Benz AG specification ☒
Accomplished: ☒

Mercedes-Benz

Service report 2
Mercedes-Benz

Bertel O. Steen Østfold AS,
Sarpsborg
Hornskinnveien 98
Sarpsborg

Date: 26.10.2018
Rep.-order-no.: 303587
Mileage: 51345 km

Performed services
Service: Service B
Workshop code: 880E
Remaining time: 90 Days
Remaining distance: ~1200 km

Oil quality/viscosity
Description: Engine oil
Oil quality: 229.52
Viscosity: 5W-30

Replaced / renewed
Engine: oil and filter change ☒
Until next service: Mercedes-Benz Mobilo ☒
Warr. against rusting through ☒
Service-intervals in accordance with Mercedes-Benz AG specification ☒
Complied with: ☒
Addwork in accordance with Mercedes-Benz AG specification ☒
Accomplished: ☒

Mercedes-Benz

Service report 3
Mercedes-Benz

Bertel O. Steen Østfold AS,
Sarpsborg
Hunnikneveien 98
Sarpsborg

Date
Rep.-order-no.
Mileage

21.10.2019
313714
65888 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service A
D00
5 Days
10457 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.52
5W-30

Replaced / renewed
Engine oil and filter change
Brake fluid replaced

☒ ☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

Mercedes-Benz

Service report 4
Mercedes-Benz

Bertel O. Steen Østfold AS,
Sarpsborg
Hunnikneveien 98
Sarpsborg

Date
Rep.-order-no.
Mileage

28.10.2020
5644652
80317 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service B
S08
10 Days
1000 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.52
5W-30

Replaced / renewed
Dust filter replaced
Air filter element replaced /
Rear axle: Oil change
Fuel filter replaced
Engine: oil and filter change

☒ ☒ ☒ ☒ ☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

Mercedes-Benz

Service report 5
Mercedes-Benz

Bertel O. Steen Østfold AS,
Sarpsborg
Hunnikneveien 98
Sarpsborg

Date
Rep.-order-no.
Mileage

11.10.2022
817171
10679 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service A
D00
5 Days
10457 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.52
5W-30

Replaced / renewed
Engine oil and filter change
Brake fluid replaced

☒ ☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

Mercedes-Benz

Service report 6
Mercedes-Benz

Slattem Kristiansund AS
Verkstedsveien 4
Kristiansund

Date
Rep.-order-no.
Mileage

11.10.2022
7719278
103679 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service B
606
8 Days
12029 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.52
5W-30

Replaced / renewed
Dust filter replaced
Engine: oil and filter change

☒ ☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

Mercedes-Benz

Service report 7
Mercedes-Benz

Slattem Kristiansund AS
Verkstedsveien 4
Kristiansund

Date
Rep.-order-no.
Mileage

05.10.2023
8995374
118107 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service A
SD0J
4 Days
10572 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.31
5W-30

Replaced / renewed
Automatic transmission: oil
and filter change
Engine: oil and filter change

☒ ☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

Mercedes-Benz

Service report 8
Mercedes-Benz

Slattem Kristiansund AS
Verkstedsveien 4
Kristiansund

Date
Rep.-order-no.
Mileage

04.09.2024
123145
128543 km

Performed services
Service
Workshop code
Remaining time
Remaining distance

Service B
ODW
28 days
14600 km

Oil quality/viscosity
Description
Oil quality
Viscosity

Engine oil
229.52

Replaced / renewed
Perform Service B with Plus
package

☒

Until next service
Mercedes-Benz Mobilo
Warr. against rusting through

☒ ☒

Service-intervals in accordance with Mercedes-Benz AG specification
Complied with ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished ☒

3 / 11
16:00

Mercedes-Benz

Digital Service Report

Vehicle Info
Vehicle: E 220 d
First reg. date: 26.07.2017
FIN: WDD2110041A155389

Next Service
08.2026 164914 km
Check your first scheduled service date in your vehicle owner's manual. Service history and service interval indicators on the performance of the Service.

Service report #
Mercedes-Benz: Stattem Kristiansund AS
Verkstedveien 4
Kristiansund

Performed services
Service: Service A
Workshop code: 505
Remaining time: 13 Days
Remaining distance: 13600 km

Oil quality/viscosity
Description: Engine oil
Oil quality: 229 52
Viscosity:

Replaced / renewed
Perform Service A with Plus package: ☒
Extra work for Service B: ☒
Replace brake fluid: ☒

Until next service
Mercedes-Benz Mobilio: ☒
Warn: against rusting through: ☒

Service intervals in accordance with Mercedes-Benz AG specification
Complied with: ☒

Addwork in accordance with Mercedes-Benz AG specification
Accomplished: ☒

KJØRETØYDATA

ANTALL NØKLER	2	ANTALL LADEKABLER	0
TIDLIGERE STØRRE SKADE	Nei	TIDLIGERE BRUK	Normal bruk

PRØVEKJØRING

PRØVEKJØRT	HASTIGHET	TESTFORHOLD
Ja	80	Tørt

DEKK OG BREMSER

PRODUKSJONSDATO SOMMERDEKK	Uke 52, 2023	PRODUKSJONSDATO VINTERDEKK	Uke 25, 2022
----------------------------	--------------	----------------------------	--------------

	VENSTRE FORAN	HØYRE FORAN	VENSTRE BAK	HØYRE BAK
MØNSTERDYBDE SOMMERDEKK (MM)	6	6	5	5
MØNSTERDYBDE VINTERDEKK (MM)	6	6	5	5

SERVICEINFORMASJON

KOMPLETT HISTORIKK	ELEKTRONISK SERVICEHEFTE
Ja	Ja
SISTE SERVICEDATO	KILOMETERSTAND
20.08.2025	139914

☒ **Kontrollert** /
 ☐ **Ikke kontrollert** /
 ☒ **Kontrollert, anmerkning**

IDENTITET

- ☒ Kjennermerke
- ☒ Understellsnummer
- ☒ Dokumentasjon utstyr/godkjenning
- ☒ Nøkler

ASSISTENTSYSTEMER OG DIAGNOSE

- ☒ Kamera
- ☒ Sensor
- ☒ Systemfunksjoner
- ☒ Diagnose
- ☒ Prøvekjøring

EKSTERIØR

- ☒ Lakk
- ☒ Antirustbehandling
- ☒ Under bil
- ☒ Panser
- ☒ Dører
- ☒ Bakluke
- ☒ Låser/tyverisikring
- ☒ Skjermer
- ☒ Speil
- ☒ Korrosjon
- ☒ Vinduspussere/-spyler
- ☒ Verktøy/nødutstyr
- ☒ Dekk/Felger
- ☒ Hjulmuttere/-bolter
- ☒ Døråpning
- ☒ Terskler/innlastningssone
- ☒ Støtfanger
- ☒ Grill
- ☒ Tak
- ☒ Frontvindu
- ☒ Vinduer
- ☒ Kanal
- ☒ Stolpe
- ☒ Alle flater
- ☒ Ladeluke/tanklokk

LYS

- ☒ Lys foran
- ☒ Lys bak
- ☒ Markeringslys
- ☒ Retningslys
- ☒ Nødsignallys
- ☒ Parkeringslys
- ☒ Refleks
- ☒ Andre lys

MOTOR

- ☒ Avgass
- ☒ Batteri(er)
- ☒ Drivstoffanlegg/-ledninger
- ☒ Dynamo/lading
- ☒ Eksosanlegg
- ☒ Elektroniske styresystemer
- ☒ Kjølesystem/vannpumpe
- ☒ Lekkasjer
- ☒ Motorfester/-demper
- ☒ Oljenivå/røykutvikling
- ☒ Service
- ☒ Startmotor
- ☒ Trekkraft
- ☒ Turbo
- ☒ Ladeluftkjøler
- ☒ Kompressor
- ☒ Dieselpumpe/dyser/gløding
- ☒ Motor

HJULOPPHENG/STYRING

- ☒ Retningsstabilitet/selvoppretting
- ☒ Ratt/styringsmekanisme
- ☒ Hjullager
- ☒ Fjærer/støtdemper
- ☒ Ledd
- ☒ Stabilisatorer/stag
- ☒ Forstilling
- ☒ Bakstilling

BREMSER

- ☒ Bremsfunksjon
- ☒ Parkeringsbrems
- ☒ Bremskraftforsterker
- ☒ Bremsvæske
- ☒ Lekkasjer
- ☒ Rør/slanger
- ☒ Skiver
- ☒ Bremseskjold

GIR OG DRIVLINJE

- ☒ Girkasse
- ☒ Differensial
- ☒ Clutch/kobling/svinghjul
- ☒ Aksler
- ☒ Fordelingskasse

INTERIØR

- ☒ Dashbord
- ☒ Instrumenter og brytere
- ☒ Midtkonsoll/midtarmlene
- ☒ Dørtrekk
- ☒ Seter
- ☒ Taktrekk
- ☒ Tepper/bekledning
- ☒ Vindusheiser
- ☒ Bilbelte
- ☒ Varme/AC/Klima
- ☒ Signalhorn/Lydsignal
- ☒ Multimedia
- ☒ Multifunksjonsratt
- ☒ Ratt
- ☒ Deksel

OPPLYSNINGER/KLARGJØRING

- ☒ Opplysninger
- ☒ Interiør
- ☒ Øvrig utstyr/klargjøring
- ☒ Annet

Det tas forbehold om mulige avvik i kontrollpunktene avhengig av biltype og modellvariant

Vilkår, tilstandsrapport

Hva som er vurdert, forutsetninger for vurderingen

Tilstandsrapporten beskriver bilens tilstand på testtidspunktet med det utstyret som var i og på bilen.

Den tekniske vurderingen av bilen er gjort med utgangspunkt i bilens alder og kjørelengde. Rapporten beskriver om bilens tilstand vurderes som normal ut fra bilens alder og kjørelengde og/eller om det er anmerkninger eller øvrige kommentarer. Kontrollpunktene som er vurdert er listet opp i rapporten.

Bilen er ikke demontert ved vurderingen, og tilstandsrapporten påpeker dermed ikke eventuelle feil som kun kan avdekkes ved demontering eller ved lengre tids bruk ut over ordinær prøvekjøring.

Kapasiteten på driftsbatteriet på el- og hybridbiler er ikke målt, og er derfor ikke en del av tilstandsrapport

Feilmeldinger som bilens produsent har gitt tilgang til og som er tilgjengelige på vurderingstidspunktet/testtidspunktet er avlest. Avlesing av feilmeldinger skjer med tilgjengelig diagnoseutstyr. Ved usikkerhet omkring feilkodene anbefales videre undersøkelser.

Bilen er prøvekjørt, men kun ved en kortere tur. Tekniske egenskaper ved bilen som forutsetter spesielle kjøreforhold er kun vurdert om kjøreforholdene på vurderingstidspunktet gjorde dette mulig.

Periodiske feil og avvik for eksempel ved oljeforbruket på fossile biler kan forekomme uten at dette kan avdekkes, ettersom vurderingen kun gir et øyeblikksbilde av bilens tilstand.

Sted og Dato

Sted og Dato

Signatur selger

Signatur kjøper

Selger og kjøper bekrefter med sine underskrifter at ved inngåelsen av kjøpsavtalen ble tilstandsrapporten gjennomgått med kjøper, og at det spesielt ble informert om avvik fra kravene i forbrukerkjøpslovens § 15 i de tilfeller slike fremkommer i rapporten, og at kjøper aksepterer disse avvikene.